Oil Field Environmental Incident Summary

Responsible Party: STATOIL OIL & GAS LP **Well Operator:** STATOIL OIL & GAS LP

Well Name: BUFORD 10-3 1H

Field Name: BUFORD Well File #: 27658

Date Incident:7/24/2016Time Incident:06:00Facility ID Number:County:WILLIAMSTwp: 152Rng: 104Sec: 10Qtr:

Location Description:

Submitted By: Derrick Dion Received By:

Contact Person: Rick Nelson

6300 BRIDGE POINT PKY, BLDG 2

SUITE 500

AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Facility SiteReported to NRC: NoSpilledUnitsRecoveredUnitsFollowupUnitsOil3.5Barrels3.5Barrels3.5barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 8/22/2016 Clean Up Concluded: 7/24/2016

Risk Evaluation:

No immediate risk to personnel

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Well has been shut in, work order in for maintenance to repair pop off valves. Spill clean-up crew onsite cleaning affected are of well site.

Wastes Disposal Location: Secure Energy

Agencies Involved:

Updates

Date: 7/25/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to equipment failure, remained on facility site according to the report. NDIC retains oversight.